


ACERA Rapidfire Plus Lever SL-M3010-L (2x9-speed)

For Left Hand



ITEM NO.	SHIMANO CODE NO.	DESCRIPTION
1	Y0D898010	L.H. Indicator Unit
2	Y6PZ98070	Cable Adjusting Bolt Unit
3	Y6CD33000	Inner Hole Cap
4	Y6TB98060	Main Lever Cover & Fixing Screw
5	Y01L49000	Clamp Bolt (M6 x 17.8)
6	Y60198090	OT-SP41 OPTISLICK shift cable sets (Black) <ul style="list-style-type: none"> • Sealed outer caps, plastic (9 pcs.) • Sealed outer cap nose (1 pc.) • Rubber shield (1 pc.) • Inner end caps (2 pcs.)
	Y60198091	OT-SP41 OPTISLICK shift cable sets (White) <ul style="list-style-type: none"> • Sealed outer caps, plastic (9 pcs.) • Sealed outer cap nose (1 pc.) • Rubber shield (1 pc.) • Inner end caps (2 pcs.)

Apr.-2017-4287

© Shimano Inc. I

Specifications are subject to change without notice.

SHIMANO